



Positive Response is a closing communication loop between an excavator and facility owner.  
 Positive Response became effective in the Ohio Revised Code (ORC) as of March 27, 2013

To access the Positive Response program you will need a username and password. If you haven't already set up a username and password you will need to contact Member Services 800-311-3692 option 6 to get your login credentials.

Once you hit the website, <http://newtin.oups.org>, you will enter your username/password. From this point you will be at the following screen

**Newtin - +Response - OUPS A (Youngstown)**

Tickets	Maintenance	Reports	System
<a href="#">+Resp</a> <a href="#">Positive Response</a> <a href="#">Response Analysis</a> <a href="#">General Access - Response Display</a> <a href="#">Response Inquiry</a> <a href="#">Response Stats</a> <a href="#">Ticket Responses</a> <a href="#">Tickets Without Response</a> <a href="#">Tickets with 004 Responses</a>		<a href="#">Monthly Member Ticket Stats</a> <a href="#">Tickets without Response</a>	<a href="#">Julian Calendar</a> <a href="#">Log Out</a>

To post responses you will click on "Positive Response" and hit the "By Response Due" tab. At that time you will be presented with a list of tickets that you need to respond by based on the 48 hours. If you need a specific ticket you will need to enter the specific # under the "By Ticket" tab.

Positive Response

**Newtin - A (OUPS Youngstown)**

Positive Response

By Ticket		By Response Due		By Response Past Due			
TKT#	Response	Code	Dig Date	County	Place	Street	
<a href="#">B115300766</a>		MAPE	06/04/21 10:08:00	BUTLER	OXFORD	3600 SOUTHPOINTE PKWY	
<a href="#">B115300766</a>		MAPW	06/04/21 10:08:00	BUTLER	OXFORD	3600 SOUTHPOINTE PKWY	
<a href="#">A115301842</a>		MAPE	06/04/21 11:18:00	AUGLAIZE	DUCHOUQUET TWP	BLACKHOOF CREEK RD	
<a href="#">A115301842</a>		MAPW	06/04/21 11:18:00	AUGLAIZE	DUCHOUQUET TWP	BLACKHOOF CREEK RD	
<a href="#">A115301905</a>		MAPE	06/04/21 11:39:00	LICKING	BUCKEYE LAKE	147 SEYMOUR AVE	
<a href="#">A115301905</a>		MAPW	06/04/21 11:39:00	LICKING	BUCKEYE LAKE	147 SEYMOUR AVE	
<a href="#">A115302228</a>		MAPE	06/04/21 12:26:00	MAHONING	CANFIELD TWP	6638 COVINGTON CV	
<a href="#">A115302228</a>		MAPW	06/04/21 12:26:00	MAHONING	CANFIELD TWP	6638 COVINGTON CV	
<a href="#">A115302336</a>		MAPE	06/04/21 12:40:00	HAMILTON	HARRISON	1097 SOUTH BRANCH	
<a href="#">A115302336</a>		MAPW	06/04/21 12:40:00	HAMILTON	HARRISON	1097 SOUTH BRANCH	

You can then enter your responses and submit to post your responses.

Newtin - A (OUPS Youngstown)									
Positive Response									
By Ticket		By Response Due				By Response Past Due			
TKT#	Response	Code	Dig Date	County	Place	Street			
B115300766	No Conflict - Underground facilities operated by this member are not in conflict based on information provided in the Excavation Request.	MAPE	06/04/21 10:08:00	BUTLER	OXFORD	3600 SOUTHPOINTE PKWY			
B115300766	Marked - Underground facilities operated by this member at the site of proposed excavation have been marked up to the privately owned facility.	MAPW	06/04/21 10:08:00	BUTLER	OXFORD	3600 SOUTHPOINTE PKWY			
A115301842	Locator Coordination - Locate request has not been completed. Locator has/will contact the excavator to coordinate markings.	MAPE	06/04/21 11:18:00	AUGLAIZE	DUCHOUQUET TWP	BLACKHOOF CREEK RD			
A115301842	Facility Owner or Operator Coordination - Locate request has not been completed. Facility Owner or Operator will contact the excavator to coordinate markings.	MAPW	06/04/21 11:18:00	AUGLAIZE	DUCHOUQUET TWP	BLACKHOOF CREEK RD			
A115301905	Work Complete - The Facility Owner or Operator or their representatives has deemed the excavation to have been completed prior to the legal start date.	MAPE	06/04/21 11:39:00	LICKING	BUCKEYE LAKE	147 SEYMOUR AVE			
A115301905	Marked - Underground facilities operated by this member at the site of proposed excavation have been marked up to the privately owned facility.	MAPW	06/04/21 11:39:00	LICKING	BUCKEYE LAKE	147 SEYMOUR AVE			
A115302228	No Conflict - Underground facilities operated by this member are not in conflict based on information provided in the Excavation Request.	MAPE	06/04/21 12:26:00	MAHONING	CANFIELD TWP	6638 COVINGTON CV			
A115302228	No Conflict - Underground facilities operated by this member are not in conflict based on information provided in the Excavation Request.	MAPW	06/04/21 12:26:00	MAHONING	CANFIELD TWP	6638 COVINGTON CV			
A115302336	Marked - Underground facilities operated by this member at the site of proposed excavation have been marked up to the privately owned facility.	MAPE	06/04/21 12:40:00	HAMILTON	HARRISON	1097 SOUTH BRANCH			
A115302336	Marked - Underground facilities operated by this member at the site of proposed excavation have been marked up to the privately owned facility.	MAPW	06/04/21 12:40:00	HAMILTON	HARRISON	1097 SOUTH BRANCH			

## OHIO811 POSITIVE RESPONSE DEFINITIONS

**001- No Conflict-** Underground facilities operated by this member are not in conflict based on information provided in the Excavation Request.

**002- Marked-** Underground facilities operated by this member at the site of proposed excavation have been marked up to the privately owned facility.

**003- Excavation Request Cancelled (CNCL) -** Excavator has cancelled this excavation request.

**004- Locator Coordination-** Locate request has not been completed. **Locator** has/will contact the excavator to coordinate markings.

**005- Facility Operator Coordination-** Locate request has not been completed. **Facility Owner or Operator** will contact the excavator to coordinate markings.

**006- High Profile or Critical Facility-** Facility Owner or Operator requests to be present for the excavation in accordance with ORC 3781.31 (A). Excavator must provide notification of at least one full working day prior to commencing excavation.

**007- Complex Project (LPRJ) -** This response is designated for use with a Complex Project notification only.

**008- Design Notification (DSGN) -** Facility Owner or Operator has completed the design request in accordance with ORC 3781.27 (C) or 153.64 (B) (2).

**009- Work Complete-** The Facility Owner or Operator or their representatives has deemed the excavation to have been completed prior to the legal start date.

**999- No Response (LATE) -** The Facility Owner or Operator or its representatives has not posted a Positive Response prior to the legal start date. A "LATE" notification has automatically been sent to the Facility Owner or Operator.